

1

Sent to Chief Surveyors 22. 6. 27Received from Chief Surveyors 24 JUN 1927VESSEL'S NAME Steel Sc. "COMBO"Report LONDONNo. 91530^a**For the CHIEF SHIP SURVEYOR and CHIEF ENGINEER SURVEYOR.**

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/22.)

Nature of Survey Boiler When due 9. 26.
Screw shaft " 12. 26.

The Boiler Survey became due in 9.26 and the examination of the screw shaft in 12.26.

The Agents state that the surveys have not taken place by order of the Directors who, they understand, do not wish to continue the vessel's class.

IT IS SUBMITTED that the vessel's class be withdrawn from the Register Book and three dots inserted in lieu thereof, indicating that the class has been withdrawn at the Owners' request.

Withdraw Class

Insert ...

J.W.D.
22. 6. 27.
J.P. *M.H.* *M.C.S.*



© 2021

Lloyd's Register
Foundation