

S.S. "COMBO"

The Special Survey No.3 of this vessel was held in December 1924 by a Surveyor appointed by Lloyd's Agent ^{at} ^{Dakar} when, confiding in this Surveyor's report, notation of S.S. No.3 was assigned.

The Bordeaux Surveyor now reports that nine plates in the vicinity of the stem have been renewed and also that a shoe plate has been fitted at the after end where the keel plates were found chafed.

It may of course happen that a vessel, the survey of which was carried out in December, will require extensive repairs in such a short time due to damage, but it is considered that if the condition which has now necessitated renewal of these plates had been noted in December, the Surveyor should have drawn attention to these parts.

In the circumstances it might be well to point this out to Lloyd's Agent at Dakar, in order that the Surveyor's attention may be drawn to the necessity of taking great care in making any surveys affided to him.



© 2021

10.10.25

Lloyd's Register
Foundation

009428-009439-0115