

24 NOV 1928

1

Received by Chief Ship Surveyor

Received from Chief Ship Surveyor

VESSEL'S NAME *Stl Se "GEORGIA"* Rpt. *Sen* No. *9640*

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/22.)

Nature of Survey

DAMAGE.

sub- to the Rudder post of the stemframe E.W repair 6.26 being specially examined at the next drydocking.

Damage through

Grounding

Sen. 9457

now repaired as follows:-

	Plates	Frames	R. Frames	Floors	Beams	Str. Plates	Dk. Plates
Renewed							
Removed and faired or repaired.....	1						
Faired or repaired in place.....		6		3			

Other items:-

vessel placed in drydock, bottom cleaned coated. minor repairs effected.

The Rudder post E.W. repair examined and found satisfactory

It is submitted the vessel is worthy to remain as classed with

record of Survey *11.26* as recommended *subject as above.*

100A.1.

11.26 Sen

Filtered for oil fuel etc

subject etc



Lloyd's Register Foundation

009440-009452-227

24.11.26