

Surveyors \_\_\_\_\_

Received from Chief Surveyors \_\_\_\_\_

NAME MONTCALM Report GLS. No. 61916

**For the CHIEF SHIP SURVEYOR and CHIEF ENGINEER SURVEYOR.**

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

Survey DOCKING When due \_\_\_\_\_

Subject to N<sup>o</sup> 4 double bottom tank and N<sup>os</sup> 1 + 2 oil fuel  
bunker tanks being examined before return to normal service

Vessel taken over by the admiralty + named "THE WOLF"

WAL  
23-1-40

In S.R.L

Deep oil fuel bunker tanks and D.B oil fuel tanks to be exd.  
progressively every 4 years.

Amend S.R.L as above regarding ex. of tanks.