

1

APR 1941

Sent to Chief Surveyors.....

Received from Chief Surveyors.....

VESSEL'S NAME..... "HUKUZYU MARU" ex "MIRAMARE" Report..... Lon..... No. 109075a

## For the CHIEF SHIP SURVEYOR and CHIEF ENGINEER SURVEYOR.

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

Nature of Survey.....

When due.....

Permanent repairs are required to indented shell plating and framing in way of No. 5 hold (s.s) and repairs to indented shell plating and framing in way of No. 1 hold (p.s) at the first convenient opportunity.

The 2nd S.S. No. 2 became due 4.40, and the year of grace has been granted.

In the attached letter the Owners write that in accordance with the trend of times there they have transferred the Classification from LLOYD'S to that of Japanese NK.

It is accordingly submitted the class of this vessel be withdrawn from the Register Book and three dots (...) be inserted in lieu, indicating withdrawal of class at Owners' request.

Withdraw class  
Insert ....

© 2021  
Lloyd's Register  
Foundation  
2. H. H.  
009721-009729-0168