

Lloyd's Register of Shipping

42 ST. SACRAMENT ST.

MONTREAL, January 31st. 19 20

LLOYD'S REGISTER
LONDON.
REC'D 16 FEB 1920
ANSP

The Secretary,

London, England.

Dear Sir:-

In reply to your letter of January 2nd,
referring to the "CANADIAN SPINNER" Montreal report No.1766
in reply I have to state that the rivetting of the
bridge side plating is as required by the rules.

Yours very truly,

W. J. Alderson



© 2021

Lloyd's Register
Foundation

004721-009729-0175

Referred to the Chief Ship Surveyor.

RM.

Also for Mr. A. Hill to note.

16 FEB 1920

M

16.2.20



© 2021

Lloyd's Register
Foundation