

Chief Ship Surveyor .....

Received from Chief Ship Surveyor .....

7 - JUL 1949

NAME "S O C R A T E S" REPORT Ant. No. 25380

Remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

ACTION is DEFERRED in this case pending receipt of the ANTWERP Surveyors report.

(15 fathoms of chain cable required to be supplied).

The ANTWERP Surveyors report (5.49), the vessel placed in dry dock, and on account of damages due to collisions previously reported, (See Lon. Rpt. No. 118281 - 5.49), repairs effected to stem and indented poop counter plating etc.

IT IS SUBMITTED the vessel is eligible to remain as classed, with record of docking 5.49, subject to (15 fathoms of chain cable being supplied).

5.49 Ant. Subject.



© 2021

Lloyd's Register  
Foundation

009743-009756-0283