

Clearly indicate the nature of the damage and the repairs made. Examination and Condition on the back of the Report is to be carefully completed and amplified if necessary in the body of the Report. Outstanding items to complete the Survey should be summarised at the end of the Report. The reasons for Repairs must be stated. Repairs on account of Damage (the alleged cause of which must be stated) should be separated

+100A1

carrying oil FP above 150°F. in

No. IN REG. BK.

09389

POSTPONED SURVEYS

BUILT

3 - 1952

REG. BK.

389

POSTPONED SURVEYS

SHIP'S NAME

BUILT

3 - 1952

LAST DOCKING

4.59

REGISTRY

L.L. CERT. EXPIRES

TONNAGE

S.S.

"EIKEN MARU"

M.S.

A.L.L. SURVEY DUE

and/or conditions
under review

Special Survey due 4.60

Main Boiler Survey due 4.60

ing items
held)

ments
agreed

Postponement of Special and Main Boiler Surveys
until the end of June, 1960 approved 31.5.60

posal

Postponement of the Special Survey until
November, 1960 (7 months after due date), when a
new oil engine is to be installed, ~~as requested~~.

*Submitted a satisfactory GE (ci. 1959) be
held afloat.*

Technical
recommendation

Ex

31.6.60

Date of
Committee

Minute



© 2021

Lloyd's Register
Foundation

009784-009795-0013