

COPY

Kobe Rpt. 9 No. 6602

LLOYD'S REGISTER OF SHIPPING

B1-56026

Port Kobe (Mukaishima)

14th April, 1959.

This is to Certify that I have

surveyed the Machinery of the S.S. "EIKEN MARU" 6,395 tons gross of Shinomiya on the 7th April, 1959 and subsequently whilst she lay in drydock and afloat at Mukaishima for Main Boiler Survey and Commencement of Engine Special Survey

and that I will transmit to the Committee of Lloyd's Register of Shipping, London, a Report stating that all recommendations made by me in connection therewith have been carried out to my satisfaction; also

that I will Recommend that in the case of this Vessel the following Survey Records be made in the Supplement to the Register Book

MBS 4,59 and ES - with date - when the survey has been completed

and that her Machinery Classification Record be continued in the Book.

Parts now examined: As part ES

(C.S. Items only)

- Propeller. All sea valves.
- Main Turbine and Reduction Gearing - all parts.
- Thrust blocks, shaft and bearings. Intermediate shafts and bearings.
- Outboard turbo generator - all parts.
- Main circulating pump. Outboard L.O. pump. Outboard condensate pump.
- Bilge pumps (1- m. eng. driven, 1- independent).
- Main auxiliary feed pumps (Total 4).
- Fire & G.S. pump. F.O. transfer pump. F.O. unit pumps.
- L.O. coolers. F.O. and Feed water heaters (Each 2 tested).

Y. Hamada
Engineer Surveyor to Lloyd's Register.
Y. Hamada

KEY TO ABBREVIATIONS

ABS	Auxiliary Boiler Survey	SGS	Steam Generator Survey
CS	Continuous Survey of Engines	SPS	Steampipe Survey
DBS	Donkey Boiler Survey	TS	Tailshaft Survey
ES	Engine Special Survey	TS (CL)	Tailshaft Survey—Continuous Liner
MBS	Main Boiler Survey	TSN	Tailshaft renewed
MES	Modified Survey of Oil Engines	TS (OG)	Tailshaft Survey—Oil Gland
OF	Fitted for oil fuel (date) FP above 150°F.		

Certificate is issued upon the terms of the Rules and Regulations of the Society, which provide that:—
The Committees of the Society use their best endeavours to ensure that the functions of the Society are properly performed and it is to be understood that neither the Society nor any Member of any of its Committees is under any circumstances to be held responsible for any inaccuracy in any report or certificate issued by the Society or by its Surveyors, or in any publication of the Register Book or other publication of the Society, or for any error of judgment, default or negligence of any of its Members or any Member thereof, or the Surveyors, or other Officers or Agents of the Society."

© 2021

FOR LONDON

009789-009795-0024