

28 OCT 1959

Received from Chief Ship Surveyor

NAME "GRANSHA" REPORT Nwc. No. 116543

ding Conditions of Class: NONE.

Appendix. (As before or None)

of Present Survey: (As before or in dry dock)

Docking: Deferred repairs to set up shell plating on account of damage (cause unknown).

Adation:

SUBMITTED record of 'DS 10,59' be assigned, subject to set up shell plates B.9, C.8, D.9 (s.s.f) and C.4, 6 & 7 and D.4, 6, & 7 (p.s.f) being specially examined and dealt with as necessary next drydocking.

DS 10,59. Subject



© 2021

Lloyd's Register  
Foundation

009789-009795-0102

4-e  
92/10/59