



# LLOYD'S REGISTER OF SHIPPING

UNITED WITH THE BRITISH CORPORATION REGISTER

Lloyds Bank Chambers,

Albert Road, Middlesbrough

Telephone: Middlesbrough 2434

4th June. 1956.

RECEIVED  
5 JUN 1956

Dear Sir,

We are in receipt of your classing letter of the 29th ultimo, respecting Middlesbrough Report No.20795 "HOLMSIDE" and have to confirm that an amended Interim Certificate has been issued, copy herewith attached.

It is noted that repair of bearing surfaces and shafting by means of metal spraying is not favourably considered by the Committee. Regarding the circumstances respecting the main circulating pump impeller shaft, we have to state that this work was done without our knowledge or consent and the Owner's Representative was advised that a recommendation would be made for a further examination. We also have to state that the shaft was sprayed only in way of the gland packing and tail bearing, and we understand that a new impeller shaft has been ordered.

Due note has been made of the contents of Circular 1933 which will be adhered to in future similar cases.

Yours faithfully,  
The Surveyors.

per:-

The Secretary.  
LONDON.



© 2021

Lloyd's Register  
Foundation

009789-009795-0119

Survey Fee (per Section 231) Damage

6

Fees applied for,

27. 4. 19 56



CLASSIFICATION

4

Noted  
add  
6-6-56

1

© 2021

Lloyd's Register  
Foundation