

29th May, 1956.

MIDDLESBROUGH

20698, 719 - As recommended.

20705 "HOLMSIDE" As recommended, except that the class has been made subject to the main circulating pump shaft being specially examined before the end of 4.57 and I shall be glad if you will issue an amended Interim Certificate.

I have to acquaint you that the repair of bearing surfaces by means of metal spraying is not favourably looked upon by the Committee and I shall be glad if you will state the circumstances in which a repair of this nature was effected. With reference to your recommendation that the shaft in question should be specially examined at the next Special Survey I have to refer you to the terms of Circular No. 1933 and shall be glad if in future similar cases you will make a definite recommendation with time limit for the defect to be specially examined or dealt with.



Lloyd's Register  
Foundation

009789-009795-0120