



LLOYD'S REGISTER OF SHIPPING

Bellmansgatan 15,

Stockholm 25th August, 1958.

RECEIVED

26 AUG 1958

Ans'd

Classn.(S)

The Secretary,
LONDON.

Dear Sir,

"CECILIA FALKLAND".

We are in receipt of your classing letter of the 19th August, 1958, in respect of our Rpt. 1 No. 11581 on the above vessel, and have to confirm that the thickness of the double bottom pipe tunnel side plates is 10.5 mm as reported. The thickness of the double bottom side girder plates is 10.5 mm between frames 35 - 100 and 8.5 mm between frames 100 - 106. The rise of floor is 100 mm. It is regretted that the last information was omitted on the report.

Yours faithfully,

THE SURVEYORS, Stockholm.



© 2021

Lloyd's Register
Foundation

CLASSIFICATION

H

Raf
SPB

noted 24/9/56
-dy.



© 2021

Lloyd's Register
Foundation