

## LLOYD'S REGISTER OF SHIPPING



Bellmansgatan 15,

Stockholm ..... 1st august, 1958.

RECEIVED

5 - AUG 1958

Ans'd

sn.(S)

The Secretary,  
LONDON.

Dear Sir,

Motorship "CECILIA FALKLAND"  
Skm. Rpt. 11581.

With reference to your letter of the 24th instant regarding the above report, we have to inform you the Surveyor states that the diameter of the screwshaft as fitted is 277 mm and regret the error made when writing the report.

With regard to the torsional endorsement, the Surveyor explains that the Engine Builders have fitted a plate stating that "The engine is not to be run continuously below 77 r.p.m.". We regret that this was indicated as a subject of class in the report and not merely as a "note".

We may add, however, that no mention was made of this barred speed range in the interim-certificate issued on completion of the vessel.

Yours faithfully,  
THE SURVEYORS, Stockholm



© 2021

Lloyd's Register  
Foundation

