

COPY

LLOYD'S REGISTER OF SHIPPING

Report No.D.8336



Port of Piraeus,

12th February, 1960.

This is to Certify that

E.F.Reid

the undersigned Surveyor to this Society did at the request of J.A.Saunders, Esq., Lloyd's Agent, Piraeus and with the consent of the Owners' Representative attend on board the

S.T. "ALEXANDROS"

5555 tons gross of Panama

whilst lying afloat at Perama, on the 2nd February, 1960, for the purpose of ascertaining the nature and extent of damage stated to have been sustained to the vessel and alleged due to

RANGING AGAINST THE M.T. "MAGEOLIA" ON THE 12TH JANUARY, 1960, AT PERAMA, GREECE.

It was stated that the "ALEXANDROS" was laid up at Perama, alongside the "MAGEOLIA", when on the 12th January, 1960 sudden gusty winds blew up causing both vessels to range and finally break moorings. Vessels were remoored on the 13th January, 1960.

No log books sighted as non available, vessel laid up. (The above information is the watchman's statement).

Upon examination by the undersigned the following damage was noted and repairs recommended without prejudice to the terms and conditions of the insurance.

FOUND:

RECOMMENDED:

- | | |
|-----------------------------------|-----------------------------|
| 1 fairlead cum bollard fractured. | To renew. |
| 3 - 9" manila ropes broken. | To renew each 120 fms.x 9". |
| 2 - 1" wire rope broken. | To renew each 90 fms.x 1". |

The above recommendations were made with a view to placing the vessel in the same good and efficient condition as before the said damage was sustained and all repairs have been deferred.

In the opinion of the undersigned the above damage is reasonably consistent with the alleged cause.

Survey fees	£ 10. 0. 0
Expenses	1. 8. 6
Stamps	3. 6

£ 11.12. 0 = Drs. 980,20 Surveyor to Lloyd's Register.

Certificate is issued upon the terms of the Rules and Regulations of the Society, which provide that:—

"While the Committees of the Society use their best endeavours to ensure that the functions of the Society are properly performed, it is to be understood that neither the Society nor any Member of any of its Committees is under any circumstances ever to be held responsible for any inaccuracy in any report or certificate issued by the Society or its Surveyors, or in any entry in the Register Book or other publication of the Society, or for any error of judgment, default or negligence of any of its Committees or any Member thereof, or the Surveyors, or other Officers or Agents of the Society."