

COPY

Received: 10.1.47.

LLOYD'S REGISTER OF SHIPPING,
MONTREAL.

AIR MAIL

6th January, 1947.

The Secretary
LONDON.

Dear Sir:-

BOILERS - "C" Type COASTERS

On looking over our First Entry Reports No. 52 for the above mentioned Vessels, we regret to state that an error has occurred in reporting the tensile strength of the combustion chamber girders as 26-30 tons/square inch, whereas this should be 29-33 tons / square inch, in each of the under-mentioned Reports:-

Montreal Report No. 6782 S/S "OTTAWA MAYHILL"

Montreal Report No. 6784 S/S "OTTAWA MAYROCK"

Montreal Report No. 6786 S/S "OTTAWA MAYTOR"

Montreal Report No. 6900 S/S "OTTAWA MAYCREST"

Montreal Report No. 6901 S/S "OTTAWA MAYBANK"

Montreal Report No. 6906 S/S "OTTAWA MAYCLIFF"

Montreal Report No. 6921 S/S "OTTAWA MAYFALL"

We will be glad if you would arrange for the necessary correction to be made.

We are, Dear Sir,

Yours faithfully,

Sgd: T. Morris

For the Surveyors

TOM:FC



© 2021

Lloyd's Register
Foundation

009879-009881-0021

For Engineer Surveyors (F.E. Rpts.) to note.

Noted L.J. 14/1/67.

COBA



© 2021

Lloyd's Register
Foundation