

Received from Chief Ship Surveyor

23 JUN 1958

SHIP'S NAME "BONAVISTA" REPORT Nfl. No. 4276

Outstanding Conditions of Class: Subject to indented shell plating
A.7, D.3, 4, 7 & 8, E.3 & 7 (s.s.) and D.4, 5, E.5, 6, F.5 (p.s.)
being examined and dealt with as necessary at next drydocking.

Endorsement of Certificate (~~As before~~ or None)

Nature of Present Survey: (Afloat and in dry dock)

Drydocking: Wear and tear repairs: Special examination, temporary and further deferred repairs to indented shell plating - deferred item above: Reported pitted bottom shell plating considered efficient meantime but recommended to be examined

Recommendation: next drydocking: Equipment (supply and verification of one bower anchor - cause not stated).

SUBMITTED record of 'DS 4,58' be assigned ^{pitted} as recommended, subject as above, and to ^{bottom} shell plating (p & s) being examined and dealt with as necessary next drydocking.

DS 4,58 Subject



© 2021

Lloyd's Register
Foundation

Blk(new)

009888 - 009895 - 0021