

"CONF ID"

Rot. 30121

Before this case receives consideration, IT IS SUBMITTED the Rotterdam Surveyors be informed that the pumping arrangements as reported do not agree with the pumping plan altered by them and forwarded with their letter of 30.6.47, as follows:-

- 1) The fore peak is reported as not being used as a ballast tank, whereas the plan shows a suction and delivery connection thereto.
- 2) The double bottom tank is reported as being in use as a ballast tank, whereas the connections on the plan have been crossed out.

In the circumstances, the Rotterdam Surveyors should be asked for their comments, and to answer the following questions:-

- 1) What are the sizes of ballast connections and air pipes to the D.B. tank.?
- 2) How is the fore peak drained.?
- 3) In view of their statement that the after peak tank is for drinking water, are the sea water connections thereto still fitted - as shown on the pumping plan.?

An amended pumping plan showing the precise arrangements as fitted should be forwarded.

Em

JRB

19. 11. 47.

Write Ref. (h 2m):



© 2021

Lloyd's Register  
Foundation

009888-009895-0084