

4E

is subject to

Further repairs to the propeller being made at the next dry docking.

ed by Chief Engineer Surveyor.....

Received from Chief Engineer Surveyor.....

BMN

6461.

ROT

No. 54201.

S NAME.....

"MEDINA PRINCESS".....

REPORT.....

(See correspondence &amp; cables).

The Bremen Surveyors recommend repairs to electrical installation, boiler lagging and fire extinguishing line and emergency fire pump be effected at Rotterdam where ship is proceeding.

The Rotterdam Surveyors report that these recommendations now satisfactorily dealt with.

IT IS SUBMITTED that this vessel is eligible to remain as classed, subject as above.



© 2021

Lloyd's Register  
Foundation

12.9.62.

009896-009903-0319