

COPY

LLOYD'S REGISTER OF SHIPPING

6461



Port

B r e m e n

17th June, 1962

This is to Certify *that I have*

Surveyed the Machinery of the S/S "MEDINA PRINCESS" 7069 tons gross of Leith, whilst the ship was lying afloat in Bremen on the 30th May, 1962 and subsequently on account of repairs (wear and tear)

~~we shall~~
and that I ~~will~~ transmit to the Committee of Lloyd's Register of Shipping, London, a Report stating that ~~all~~ ^{the following} recommendations ~~made~~ ^{were} by me in connection therewith have been carried out to my satisfaction, also ~~and~~
that I ~~will~~ Recommend that in the case of this Vessel the following Survey Records be made in the Supplement to the Register Book

and that her Machinery Classification Record be continued in the Book, without fresh record of survey, subject to the fire extinguishing line being placed in good condition, the emergency fire pump being placed in good condition, the lagging on the boilers being satisfactory restored, the generators to be cleaned as necessary, the ammeters of the outer generator to be overhauled and the earth faults on the outgoing cables from the switchboard being dealt with, the lighting in the E.R. and B.R. to be permanently restored and all temporary lighting to be removed or made permanent at Rotterdam to which port the ship is now proceeding direct from Bremen

Parts now examined:

(C.S. Items only) X

KEY TO ABBREVIATIONS

ABS Auxiliary Boiler Survey
CS Continuous Survey of Engines
DBS Donkey Boiler Survey
ES Engine Special Survey
MBS Main Boiler Survey
MES Modified Survey of Oil Engines
OF Fitted for oil fuel (date) FP above 150°F.

SGS Steam Generator Survey
SPS Steampipe Survey
TS Tailshaft Survey
TS(CL) Tailshaft Survey—Continuous Liner
TSN Tailshaft renewed
TS(OG) Tailshaft Survey—Oil Gland

This Certificate is issued upon the terms of the Rules and Regulations of the Society, which provide that:—

"While the Committees of the Society use their best endeavours to ensure that the functions of the Society are properly executed, it is to be understood that neither the Society nor any Member of any of its Committees is under any circumstances whatever to be held responsible for any inaccuracy in any report or certificate issued by the Society or its Surveyors, or in any entry in the Register Book or other publication of the Society or for any error of judgment, default or negligence of any of its Committees or any Member thereof, or the Surveyors, or other Officers or Agents of the Society."

(Cert. B.1.) 150m,5.60 (MADE AND PRINTED IN ENGLAND)

Engineer Surveyor to Lloyd's Register

© 2021

Lloyd's Register
Foundation

009896-009903-0325