

Received from Chief Ship Surveyor

SHIP NAME "BENVANNOCH"

REPORT (Gib.
(Lon:
(Mdb:No. 3664
No. 125837
No. 19796

Standing Conditions of Class: NONE.

Endorsement of Class (B) (As before ~~or~~ None)

Area of Present Survey: (Afloat and in dry dock)

Renewal of rudder.
Repairs to fractured
sternframe sole piece
as above.

Recommendation:

SUBMITTED record of docking 12,52 be assigned
as recommended, subject to repairs to sternframe
sole piece being **specialty** examined at the next
drydocking.

12,52 Mdb. Subject.

ENDORSEMENT OF CLASS (B)

No.4 shell plate in 3rd below sheer (s.s.).
Shell plates A.3 & 4 (s.s.) slightly set up.

It is further submitted the Surveyor
be requested to forward the foregoing
certificates which do not appear to
have been attached to the report.

P.T.O.

C.S.S. Records Dept.

Lloyd's Register

Received from Chief Ship Surveyor

No. 12587
No. 1933

REPORT a (1p)
No. 12587
No. 1933

NAME "BEWANNON"

standing Conditions of Class: NONE.

The Surveyors' recommendation about repairs to broken sternframe being dealt with as an Endorsement of Class (B) is not concurred in - refer Circular No. 1707A and it is submitted they ^{should} be advised - refer the enquiry in letter of 6.2.53.

Renewal of rubber.
Repairs to fractured
sternframe and place
as above.

(Afloat and in dry dock) Survey: 5 of Present

LL

SUBMITTED record of holding 12.53 be assigned as recommended, subject to repairs to sternframe and place being examined at the next drydocking.

12.53 Subj.

P.T.O.



© 2021

Lloyd's Register Foundation

Don
Ver
Ex
ha
ge
W.
A
Re
St
SUM
PRES
Deck
Caulk
Coam
Beam
Outsi
"
Fram
Rever
Long
Trans
Floor
Keels
String
Inner
Have
Have
Gen
Th
ol