

Chief Surveyors.....

Received from Chief Surveyors.....

EL'S NAME....."COTTONWOOD CREEK".....Report.....N.Yk. No. 47882.....

**For the ~~CHIEF-SHIP SURVEYOR~~ and CHIEF ENGINEER SURVEYOR.**

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinet summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

of Survey..... When due.....

The New York Surveyors now report the machinery has been generally examined with a view to Classification with this Society.

Parts of the machinery have been examined and electrical installation megger tested.

The latest records available in this office regarding the surveys held by the American Bureau are BS 3.47, MS 3.47 and screw shaft seen 6.45 (CL).

Insert in Register Book:-

Classification Contemplated

"Examined 6.47"



© 2021  
*Yhar*

4. 8. 47.

Lloyd's Register  
Foundation

009904-009911-0058