

19 APR 1933
19 APR 1933

Ship Surveyor

Received from Chief Ship Surveyor

NAME Steel Tw. Sc. M.S. "ENUKIDSE" Rpt. Lis No. 2248

Reports of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/32.

by

The Lisbon Surveyor reports this vessel examined afloat on account of damage (cause not stated).

No.4 (boiler feed water) and No.5 (piston cooling water) double bottom tanks fitted with short sounding pipes.

The Surveyor recommends No.4 port and starboard and No.5 double bottom tanks be thoroughly cleaned and longer sounding pipes be fitted on vessel's arrival at Odessa.

It is submitted the vessel appears worthy to remain as classed without record of survey subject as recommended.

As now: subject &c.

[Handwritten signature]
10-4-33