

2m,6,54

4E

Received by Chief Engineer Surveyor

Received from Chief Engineer Surveyor

SHIP'S NAME

"CANADIAN VICTOR"

REPORT

Mtl .

16 JUL 1957
No. 11616

The remarks of the Chief Engineer Surveyor are desired on this case for the consideration of the Classing Committee.

(The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement.—Extract from Sub-Committee's Report, 24/5/52.)

Nature of Survey

REPAIRS TO ENGINES AND BOILERS DUE TO DAMAGE THROUGH

ES due 5,57, partly held 5,57, now advanced.
MBS due 5,57, partly held 5,57, now complete.

IT IS SUBMITTED that this vessel will be eligible for the record ES 6,57 when the Survey has been completed, MBS 5,57 now.

To complete the ES:-

See Form 10E.

Uth *Ent*

12.7.57



© 2021

Lloyd's Register
Foundation

010024-010036-0314