

LLOYD'S REGISTER OF SHIPPING

UNITED WITH THE BRITISH CORPORATION REGISTER

FOUNDED 1760

RE-CONSTITUTED 1834

Certificate of Class

Steel Screw Motorship

"ISEBEK"

Official Number — Port of Registry Hamburg

Owners Partenreed M/S "Isebek" (Knöhr & Burchard NfL. Managers)

Builders, and where and when built D.W. Kremer Sohn Schiffswerft, Elmshorn, April, 1952

REGISTERED PARTICULARS

Length	166.43 feet	Tonnage, Gross	497.5
Breadth	29.16 feet	Ditto under Deck	374.0
Depth	10.89 feet	Ditto Net	270.0

This is to Certify that this Ship has been built under the Special Survey of the Surveyors to this Society, and was reported to be, on the 17th April, 1952 in a fit and efficient condition as is prescribed by the Society's Rules for the safe carriage of dry and perishable or other approved Cargoes, and has been CLASSED and entered in the REGISTER BOOK of this Society, with the Character  100A1 Carrying Petroleum in Bulk.

subject to Periodical Surveys as required by the Rules.

Part Electrically Welded.
Longitudinal Framing.
Strengthened for Navigation in Ice.

The approved minimum freeboards from the deck line are as follows:—

Tropical	— feet — inches (T).	Winter	} — feet — inches (WNA).
Summer	— feet 9½ inches (S).	North Atlantic	
Winter	— feet — inches (W).	Allowance for fresh water for all freeboards	} — inches

Witness my hand,

P. Ebliment
Secretary.


W. Hoppe
for Chairman.

71, Fenchurch Street, London, E.C.3. 22nd August, 1952

N.B.—If the ship herein named proceed to sea with a less freeboard than that approved by the Committee, or if the freeboard marks be obliterated or placed higher than the correct position, the class will be liable to be forfeited.

This Certificate is issued upon the terms of the Rules and Regulations of the Society, to which Owners are referred, and which provide that:—

"While the Committees of the Society use their best endeavours to ensure that the functions of the Society are properly executed, it is to be understood that neither the Society nor any Member of any of its Committees is under any circumstances whatever to be held responsible for any inaccuracy in any report or certificate issued by the Society or its Surveyors, or in any entry in the Register Book or other publication of the Society, or for any error of judgment, default or negligence of any of its Committees or any Member thereof, or the Surveyors, or other Officers or Agents of the Society."



Lloyd's Register
Foundation



© 2021

Lloyd's Register
Foundation

010037-010045-0548