

30 MAR 1931

Twin Sc. "IRWIN".



The Annual Survey of the water tube boilers became due in August last.

In reply to inquiry, the Colombo Surveyor has forwarded a copy of the letter received from the Owners in which they state that the survey has been held by the Government Surveyor at Colombo and it is not proposed to carry out a separate survey for this Society.

IT IS SUBMITTED the vessel's class be withdrawn from the Register Book and three dots inserted in lieu, indicating withdrawal of class at Owners request.

Withdraw Class

Insert ...


25. 3. 31.




© 2021

Lloyd's Register
Foundation

010079-010088-0009