

Twin S.S. "IRWIN".

--

The damage report of the survey held by the Society's Surveyor at Colombo on the machinery of this vessel was at the request of Lloyd's Agents acting for the Salvage Association.

The question as to the cause of the damage has nothing to do with the classification of the ship or her machinery.

Spk
Spk
X

[Handwritten signature]

ARK

7.1.30.

© 2021

Lloyd's Register
Foundation