

(Received at London Office)

19.....)

Place Mukaishima Shipyard of
Hitachi Shipbuilding & Date Aug. 9th., 19 58
Engr. Co., Ltd.

We request that the Committee of Lloyd's Register will instruct the
Society's Surveyors to Specially Survey during Construction the Hull, Engines and
Machinery of the Vessel No. 3873 building by Messrs. Hitachi Shipbuilding &
Engineering Co., Ltd. for Messrs. V/O "SUDOIMPORT" MOSCOW, U.S.S.R.
about 500 Tons. Length 47.00 M, Breadth 9.00 M, Depth 4.20 M

to be Classed + 100 A 1 for "Strengthened for Navigation in Ice
Class 3" & + LMC.

We undertake to arrange for every facility to be given to the Surveyors
to carry out the duty in question, and we agree to pay the fees for the Surveyor's
services, in addition to the actual travelling and other expenses incurred by the
Surveyors in connection therewith.

This request is made upon the terms of the Rules and Regulations of
Lloyd's Register of Shipping, which provide that:—

"While the Committees of the Society use their best endeavours to ensure that the functions of the Society are properly
performed, it is to be understood that neither the Society nor any Member of any of its Committees is under any circumstances
to be held responsible for any inaccuracy in any report or certificate issued by the Society or its Surveyors, or in any
entry in the Register Book or other publication of the Society, or for any error of judgment, default or negligence of any of its
Committees or any Member thereof, or the Surveyors, or other Officers or Agents of the Society."

Engine Makers Hitachi Shipbuilding & Engineering Co., Ltd.

Boiler Makers

Signature

T. Inoue

the Secretary,

Lloyd's Register of Shipping,

71, Fenchurch Street, London, E.C.3.

Manager of Head Design Office of
Hitachi Shipbuilding & Engineering
Co., Ltd.

To avoid misunderstanding, orders for materials requiring to be tested should be marked as follows:—

"Inspection and Testing by Lloyd's Register Surveyors to the Society's requirements."