

W. A. PHILLIPS, ANDERSON & CO., LTD.

HEAD OFFICE:  
7, STRATTON ST., LONDON, W.1.

GROSVENOR 4721-2-3

TELEGRAMS: "PHILANCO-PICCY, LONDON"

YACHT & BOAT BUILDERS  
SHIP REPAIRERS  
ENGINEERS

MEMBERS

BOAT BUILDERS EXPORT GROUP

THE SHIP & BOAT BUILDERS ASSOCIATION

ON THE APPROVED LIST OF AGENCIES ISSUED BY THE DIRECTOR OF SMALL CRAFT DISPOSALS

SHIPYARDS AT  
WEST HARBOUR ROAD, GRANTON  
PHONE: EDINBORO 89191/2

SLIPWAY & WET DOCK  
DYSART HARBOUR, FIFE  
PHONE: DYSART 5404

CTORS:  
L. PHILLIPS, (MANAGING)

DAY.  
A. POULTER.

ETARY:  
UGO CAVE, M.A., F.C.A.

2nd April, 1948.

Lloyds Register of Shipping,  
31-32, Oxford Street,  
Southampton.

For the attention of Mr. Robertson

Dear Sirs,

Trawler "URANIA" - M.M.S. 1084.

You may recall that during the conversion work on the above vessel it was necessary at one period to dry dock for repairs to the ship owing to a defective bolt under the belting having caused a leak to the Engine room.

We have been asked by Underwriters to obtain Lloyds Surveyor's endorsement of the accounts for this work and we presume that they mean your endorsement that the work was carried out to Lloyds specification.

We are, therefore, enclosing these accounts and trust you will be able to make the necessary endorsement. We believe that this is necessary owing to the fact that Underwriters did not arrange for their own survey at the time.

Yours faithfully,  
For and on behalf of,  
W.A. PHILLIPS, ANDERSON & CO. LTD.

*pp. J. Venus  
Ed.*

SHIPS' MANAGER.



© 2021

Lloyd's Register  
Foundation

ENC. Accounts.

6/4/48

It is requested that  
the matter might be dealt  
with by the London Office  
This repair was satisfactorily  
carried out under our supervision  
& entailed considerable financial  
& replacement for same.

Submitter mess W A Philips  
be advised as above J. H. P. → Underwent to  
J. H. P. 6.11.48



© 2021

Lloyd's Register  
Foundation