

COPY.

Lloyd's Register of Shipping,

71, Fenchurch Street, E.C. 3.

15th

~~2nd~~ September, 1926.

Dear Sir,

E. With reference to Vancouver Report No.1651 on the Electric Lighting Installation of the M.V. "MARVOLITE" I have to request that you will state whether the sizes of the cables and their respective loads are correctly reported, the amperages, except in the case of the cargo light cables, being greater than the maximum allowed by Table I of the Rules for the sizes of the cables as reported.


It is concluded that 11 joints in cables are made in joint boxes as required by Section 6, Par.4 of the Rules and that the soldering of cables mentioned in the Report refers only to soldered sockets for cables .04 square inch area and above, but I shall be glad if you will confirm this.

A supply of new forms for reporting electric light installations is being forwarded to you, under separate cover, and I shall be glad if you will use these forms in future cases.

I am, Dear Sir,
Yours faithfully,

A.Scott Esq.,

VANCOUVER, B.C.



Lloyd's Register
Foundation

010219- 010228 - 0164