

S.S. "CARIBBEAN TRADER" (Continued)
=====

FOUND

Nos. 3, 4, 5 & 6 bulwark stays,
starboard side, numbered from
aft, buckled.

Stringer plate, aft deck,
starboard side, set down in way
of Nos. 3, 4 & 5 bulwark stays
from aft.

RECOMMENDED

To remove, fair and refit.

To fair in place.

The foregoing recommendations were made with a
view to placing the hull in the same good and efficient condition
as before the alleged casualty occurred and repairs have been
deferred until next drydocking.

John Douglas

Signed: J.N.P. Douglas.

SURVEYOR TO LLOYD'S REGISTER.

Fee Ptas. 2.000.-

Exp. " 1.150.-



© 2021

Lloyd's Register
Foundation