

Chief Surveyors.....

Received from Chief Surveyors.....

NAME "CARIBBEAN TRADER" REPORT Bal. No. 11532

For the CHIEF SHIP SURVEYOR ~~and CHIEF ENGINEER SURVEYOR~~

In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—(Extract from Sub-Committee's Report, 24/5/92).

of Survey Docking: S.R.L: ~~When due~~
Deferred damage repairs.

NOTED.

Subject to indented stern plating and indented bulwark plating abreast No.4 hatch (p.s.) being specially examined and dealt with as necessary at the next drydocking.

CRM
18-2-59.



© 2021

Lloyd's Register
Foundation

010236-010245-0168