



Lloyd's Register of Shipping

231 St. James Street West,

Montreal.

October 30th, 1943

The Secretary
LLOYD'S REGISTER OF SHIPPING
71 Fenchurch Street
London, E. C. 3 - England

LANSDOWNE PARK

Dear Sir;- 4,700 Ton Cargo Vessels

This will confirm the following cablegrams which have passed between us, regarding the Stream Anchors for the above Vessels;-

Copy of Cable received;

QUEBEC REPORT 5893 CABLE IF THICKNESS STRAKE BELOW SHEER IN WELLS WITHIN MIDSHIPS HALF LENGTH POINT FIVE FIVE INCHES ALSO IF BOTTOM IN TANK UNDER BOILERS COATED WITH CEMENT OR APPROVED COMPOSITION STOP STOCKLESS STREAM ANCHOR SHOULD BE FIFTEEN CWT

Copy of Cable sent;-

RETEL QUEBEC REPORT 5893 CONFIRM THICKNESS STRAKE BELOW SHEER IN WELLS WITHIN MIDSHIPS HALF LENGTH POINT FIVE FIVE INCHES STOP BOTTOM IN TANK UNDER BOILERS COATED BITUMASTIC SOLUTION AND FINISHED BITUMASTIC ENAMEL STOP EIGHTEEN STREAM ANCHORS ORDERED IN ERROR BY WMSL AT TWELVE CWTs CONTRACT RECENTLY AMENDED TO FIFTEEN CWTs THEY REQUEST ACCEPTANCE OF ANCHORS ALREADY MADE RANGING FROM 1476 to 1563 POUNDS

Your decision has been passed on to Wartime Merchant Shipping Limited, who are grateful for the action taken by the Committee in this matter,

We are, Dear Sir,

Yours faithfully,

Whidell
SURVEYOR

ARR:FC



© 2021

Lloyd's Register
Foundation

010236-010245-0174