

10.9.43.

MONTREAL

RETEL QUEBEC REPORT 5893 CONFIRM THICKNESS STRAKE
BELOW SHEER IN WELLS WITHIN MIDSHIP HALF LENGTH POINT FIVE
FIVE INCHES STOP BOTTOM IN TANK UNDER BOILERS COATED
BITUMASTIC SOLUTION AND FINISHED BITUMASTIC ENAMEL STOP
EIGHTEEN STREAM ANCHORS ORDERED IN ERROR BY W.M.S.L.^x AT
TWELVE HUNDREDWEIGHTS CONTRACT RECENTLY AMENDED TO FIFTEEN
HUNDREDWEIGHTS THEY REQUEST ACCEPTANCE OF ANCHORS ALREADY
MADE RANGING FROM 1476 TO 1563 POUNDS

13.0.20

13.3.25

RIDDELL

Lloyd's Register
Marine Insurance Co. Ltd.

010236-010245-0176