

offered his services for this purpose, and why they were declined *Yes, not regd*

Was a damage report made by anyone else? If so, by whom? *Sur to Lou Sal Assoc*

Did the Surveyor personally go inside each Main Boiler separately and make a thorough examination?

TELEGRAPHIC ADDRESS:
KINCO, CARDIFF.
TELEPHONES:- 3208-3209.

CODES:
SCOTT'S 10TH EDITION,
WATKINS' & APPENDIX,
A.B.C. 5TH EDITION.

NEWCASTLE OFFICE:
DERWENTWATER CHAMBERS
33, SANDHILL.
TELEGRAMS:- "REDLANDS"

GLASGOW OFFICE:
87, ST VINCENT ST.
TELEGRAMS:- "REDLANDS"

HULL OFFICE:
CROWN CHAMBERS,
TELEGRAMS:- "REDLANDS"

PORT TALBOT OFFICE:
KING & WINKS,
STATION ROAD,
TELEGRAMS:- "WINKS"

DIRECTORS:
H.O. KING, H.T. KING, L.F. WINKS.

KING & CO. (CARDIFF) LIMITED.

CADOGAN HOUSE,

CARDIFF.

March 12th, 1925.

WHW/LEW.

LLOYD'S REGISTER
Recd. 13 MAR 1925
Ansd.
LONDON

The Secretary,
Lloyds Register of Shipping,
71, Fenchurch Street,
LONDON. E.C.3.

Dear Sir,

S.S. "POLMINA". REFERENCE: "H".

We are in receipt of your letter of the 11th inst., with reference to the Special Survey No.2. of the above steamer, which is now due, but in reply we regret to inform you that this vessel is ^{at} not present laid up at Cardiff, as it is impossible to run her profitably under the freight conditions ruling at the moment, and therefore it will be a distinct hardship to have to carry out this survey immediately.

We would accordingly esteem it a favour if you would, under the circumstances, kindly ask your Committee to allow us the benefit of the year of grace in which to effect this survey, and thanking you in anticipation, we beg to remain,

Yours faithfully,

for and on behalf of
KING & CO. (CARDIFF) LTD.

W.H. Williams © 2021



Lloyd's Register
010283-010288-0030

FOUNDATION
James Murdoch
Engineer Surveyor to Lloyd's

Traveling Expenses (if chargeable)..... £

Received by me
W.H. Williams
1925

Committee's Minute

TUES. 29 DEC 1925

FRI. 26 MAR 1925

TUES. 12 JUN

adjusted under steam?
adjusted under steam?
Donkey Boiler?
Donkey Boiler?
Donkey Boiler?
Hance fitted at the aft
of it being efficiently l

at the after end of
ciently lubricated?
wooded,
complete
after learn
the follow

and colle
d auxiliar
Valves, h

ud ju.
the pressu

of this ve
Book, consequent
ple, B.S. 9,11, B.
to reu
entered,

Referred to Mr. S. A. Hill.

CSA

13 MAR 1915

ho 2 due 2.25

KING & CO. CYRILL LIMITED
CVRDILL



© 2021

Lloyd's Register
Education

offered his

was a damage

Did the Surveyor I

Do.

If this was not do

And what parts of

Also what special

Surveyor to ass

Did the Surveyor

Did the Surveyor

Did the Surveyor

Did the Surveyor

Has screw shaft

Has shaft now b

is the shaft now

State the distance

If the Survey is n

Done

foreign

exam

exam

dec

four

man

and

man

man

date

but

General C

(State clearl

any a

Ido th

as now

class

Repairs

Traveling Expens

per S

per S

per S

Assigned