

Damage Repairs & etc.
Was Damage Report issued? Yes. Int. Cert.? Yes.
Last Report (For Head Office only)

12.50
2nd deck E W.
SS Shl. 9.54
TS CL
sps

4E

19 MAY 1958.

Received by Chief Engineer Surveyor..... Received from Chief Engineer Surveyor.....

SHIP'S NAME OAKBY REPORT NAGASAKI No. 856

Class is subject to buckled + torn boiler uptakes + base of funnel being renewed, centre nest of air heater tubes in stbd. boiler being renewed on vessel's arrival at Japanese port via Korea, also to permanent repair to stbd. boiler main feed entrance + to centre boiler centre furnace wrapper plate at earliest convenience
MBS due 7.57, partly held 8.57, now completed
SPS due 9.60, now held
spl All above items now dealt with

It is submitted that
this vessel is eligible for
THE RECORD.

MBS 8.57

SPS 3.58

without spl. condition



19 MAY 1958

© 2021



Lloyd's Register
Foundation

Date of Committee

THURSDAY 22 MAY 1958

Decision

MBS 8.57 without spl. con.
SPS 3.58