

3m.10.53.

Received by Chief Ship Surveyor _____
GB

Received from Chief Ship Surveyor _____

SHIPS NAME Twin Sc. Survey Ship "PATHFINDER" REPORT Lgs. No. 1069

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—*Extract from Sub-Committee's Report, 24/5/92.*)

This ship was built at Southampton in April 1954 to be classed 100A1 "For Nigerian Coasting Service", and the class was deferred until a report was received from the Surveyor at Lagos of the satisfactory condition of the ship after arrival at Nigeria.

A Report 8 has now been received from Lagos stating that a satisfactory examination has been held on the ship.

IT IS THEREFORE SUBMITTED the ship is eligible to be classed:-

*100A1 "For Nigerian Coasting Service"
4,54 Sou."Fitted for oil fuel 4,54 F.P. above 150°F"

For further particulars see Endorsement on First Entry Report dated 14.6.54.

10
6.8.54.



© 2021

Lloyd's Register
Foundation

010289-010293-0167