

SEPH W. ISHERWOOD & CO LTD

S.A. 17 BATTERY PLACE NEW YORK.

DIRECTORS:-
SIR JOSEPH W. ISHERWOOD, BT
WILLIAM ISHERWOOD.
H. C. TENNANT.
J. W. STEWART.

4, Lloyd's Avenue,
London, E.C. 3.

12th September, 1927.

Secretary,
Lloyd's Register of Shipping,
Lloyd's Bank Chambers,
MIDDLESBROUGH.

Dear Sir,

Richardsons, Westgarth & Co. Ltd.
Machinery No. 2573.

We have received from the above Engine Builders,
copy of your letter to them of the 9th inst., and a copy of
their reply of the 10th inst., regarding the fitting of Cutless
Rubber Bearings to the "A" brackets for the above machinery.

With regard thereto, we have to advise you that
these cutless rubber bearings are being fitted at the request
of the Owners, the Gulf Refining Company, who, as a matter of
fact, have supplied the bearings themselves.

Trusting this is the information you require,

We are - Yours faithfully,
SIR JOSEPH W. ISHERWOOD & CO. LTD.


Joseph W. Isherwood
Director.



© 2021

Lloyd's Register
Foundation

010300-010308-0051



Received by Lloyd's Register

Received by Lloyd's Register



© 2021

Lloyd's Register
Foundation

RECEIVED BY LLOYD'S REGISTER MIDDLESEX.COM

971300 8000W81H21 V100

HEADARTICLE
MS: RIC
ONE NO

Our
You

RALTY

DON:

ey Hou

street,

Westlo

POOD

Y Lane

Liverpo

GOW

nt Sire

lasgo

DIFF:

(ine)

Buildi

. Card

DIFF:

ND)

nt Statu

Street

By Card