

HIKAWA MARU.

YKA. 4520.

It is submitted the Surveyors be
requested to state whether the
Pneum shafts are fitted with
continuous liners for the full
length of the Stern tubes as this
arrangement was shown on the
plans of shafting submitted by
the Engine makers.

G. H.

010364 - 010377 - 0033

576/10

Lloyd's Register
Foundation

Handwritten signature and a diagonal line.



© 2021

Lloyd's Register
Foundation