

Lloyd's Register of Shipping,

(MEIKAI BUILDING)

32, AKASHI-MACHI,

KOBE, 23rd. April 1929.

Cert. No. 1956.

This is to Certify that at the request

of Messrs. The Kobe Steel Works Ltd., Kobe.

the Open Hearth Steel Forgings or Castings named below ^{were} examined and tested at their works on December 24, 1928 to April 18, 1929 (9 visits)

and found to be as far as could be ascertained, sound and free from defect.

One propeller shaft 460 m/m dia. minimum under liner fitted with a continuous liner in one piece and a propeller nut for that shaft.

Drop tests: Examined in finished condition except the cone for propeller (which is rough turned)

Note: The space between shaft and liner is charged with red lead solution.

Test Mark	Tenacity Tons/sq in	Elongation % in 2"	Bend 1" x 3/4", 180°
SHAFT C 2701A1	30.2	34	Good
NUT D 3082A3	30.6	31	"

These forgings are intended for Yokohama Dockyard

Ship No. 177-8

and ^{has} been stamped as follows:-

Fee Yen 85.00

Expenses „ 4.00

177
C2701A1, D3082A3
LLOYD'S
No. 1956
18.4.29
L.R. A. W.

Awatt

Surveyor to Lloyd's Register.

This Certificate is issued upon the terms of the Rules and Regulations of the Society, which provide that:--

"While the Committee use their best endeavours to ensure that the functions of the Society are properly executed, it is to be understood that neither the Committee nor the Society are under any circumstances whatever to be held responsible for any inaccuracy in any report or certificate issued by the Society or its Surveyors, or in any entry in the Register Book or other publication of the Society or for any error of judgment, default, or negligence of the Surveyors, other Officers or Agents of the Society"

(WEIKAI VUIGING)

35. AKASHI-ISHAKA

KOBE, 8249, 46177 1083.

Thereto at the

Measure. The X-ray stress works Ltd. X-ray.

[illegible][illegible]

to stop more, so far from being, furnished as they are of such

Only bottle Toni's reds machine. 45 Wm Old 41765 Tel. 67070 and

the following information was obtained from the records of the Bureau of the Census:

2/24/1944
 Approved by the Board of Directors
 2/24/1944

✓ (Name of donor or holder) Telephone number

NOTES AND BY

Leaf Mark	Located in Tension	% in Elongation	Temp °C
11073 D	3.02	40	8003
618003 D	3.02	12.2	"

ГОРОДА МОСКВА

rot
bebratur.

01 001201 00007

\therefore swallow and fragments read $\frac{\text{swallow}}{\text{read}}$ form.

8-111, on file

8498067 1410780

1018

1948.4.10

U. S. R. I.

170

Wm. Lloyd Garrison

THIS Certificate is issued upon the return of the Rules and Regulations of the Society, which provide that:

"While the Committee use their best endeavours to ensure that the functions of the Society are properly executed, it is to be understood that neither the Committee nor the Society are under any circumstances whatever to be held responsible for any financial

Building the Book Register in the United States and in the United Kingdom, 1840-1860