

THROUGH YOKOHAMA

COPY

LLOYD'S REGISTER OF SHIPPING

71, Fenchurch Street, London, E.C.3

Telegrams: Committee, London, Telex
Telex No.: 24305

Telephone: ROYal 9166

2nd May, 1960

ssn. (S)
V/KL

Dear Sirs,

Steamer "CAILLY"

A report has been received from the Lloyd's Agents at Casablanca in respect of a survey carried out by a Surveyor appointed by them when this vessel was in drydock in February. As a result of this inspection the Committee have continued the class subject to indented shell plates A.2 and B.1 (port side forward), and shell plating in way of oil fuel tanks (port and starboard) being specially examined by the Special Survey.

I take this opportunity to inform you that the class is also subject to shell plate No. 1 in 2nd below sheer (starboard side forward) and adjacent shell plate No. 2 being specially examined and dealt with as necessary, also to extensive scaling being carried out to shell plating, deck plating and hatch coamings by the Special Survey.


In the meantime fresh records of Docking Survey 3,60 and Main Boiler Survey 1,60 have been assigned.

Yours faithfully,

c.c. Yka.

pro Clerk to the
Classification Committee.

The Eddie Steamship Co. Ltd.,
8, Lane 34,
Kaifeng Street, 1,
Taipeh,
FORMOSA.



© 2021

Lloyd's Register
Foundation

010405-010415-0125