

26 APR 1960

SHIP'S NAME "CIALLY" REPORT Ham. No. 9245

GB

Outstanding Conditions of Class:

SUBJECT to shell plate No.1  
in 2nd below sheer (s.s. from fwd) and to adjacent shell plate  
No.2 being dealt with as necessary at next drydocking.

S.R.L. Appendix. (As before ~~xxxxxx~~)Nature of Present Survey: (Afloat and in dry dock)

Docking: Wear and tear repairs.

Recommendation:

SUBMITTED record of 'DS 2,60' be assigned,  
subject to shell plate No.1 in 2nd below sheer  
(s.s.f) and adjacent shell plate No.2 being  
specially examined and dealt with as necessary,  
also to extensive scaling being carried out to  
shell plating, deck plating and hatch coamings,  
by the Special Survey.

DS 2,60 Subject  
Amended.

IN S.R.L. APPENDIX.

Indented plating (p &amp; s).

Bulwark plating slightly indented.



© 2021

Lloyd's Register  
Foundation

010405-010415-0133