

WOKINGHAM COPY

-7  
ary  
EHP

LLOYDS REGISTER BILBAO (SPAIN)

(20.11.43.)

REPORT 9628 CABLE CONFIRMATION ONLY TWO BOWERS ABOARD  
IF SO GIVE RECOMMENDATION REPLACEMENT MISSING ANCHOR  
ALSO FORWARD STATE SURVEYORS REPORT DRYDOCKING STOP  
REPORT 9624 CABLE MEAN DIAMETER WORN CABLE STOP REPORT  
9584 REPLY AWAITED MY CABLEGRAM ELEVENTH INSTANT

LLOYDS REGISTER



© 2021

Lloyd's Register  
Foundation

010461-010465-0114