

Received by Chief Ship Surveyor.....

Received from Chief Ship Surveyor.....

VESSEL'S NAME s.s. "THAMESFIELD"

REPORT Sld.

No. 33820

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5, 32.)

1st Long. No. ....

Depth "d" .....

2nd Long. No. ....

Proportions =  $\frac{L}{D}$  13.2

Framing As approved

Sheerstrake As approved

Sister vessel to the "EMPIRE AIRMAN", "EMPIRE MARVELL",  
"EMPIRE COLERIDGE", "EMPIRE COLLINS" & "WEARFIELD".

Two longitudinal bulkheads are fitted.

This vessel appears to have been built in accordance with the  
Rules and the approved plans, and it is submitted she is eligible to

be classed ~~EL~~100A1 "Carrying Petroleum in bulk" "Fitted for oil fuel 11.43  
FP above 150°F" 2.4.

1 Dk "Longitudinal framing" "Butts of sheerstrake & fwd side shell plating  
elec. welded"


Cell DB u E 55' 87t, DTf31' 613t, FPT 322t, APT 205t

FK, 13BH, Lloyd's A &amp; CP

P 109' F 38'

Mchy aft

O.L. 503.8'

e†  
2 1/4"

of Anchors

The class is assigned and maintained upon the understanding that the equipment will be made  
to accord with the requirements of the Rules when the present state of emergency has passed.

Insert in S.R.L:- (A bower anchor to be supplied). *Scale 1/20*



© 2021

Lloyd's Register  
Foundation  
12.11.43.