

"OTTAWA MAYHAVEN"

Rpt. Mtl. No. 6933

It is SUBMITTED before this case receives consideration a reply from the New York Office to the Secretary's letter of the 19.9.46 and cablegram of the 9.10.46 regarding the Service limits be awaited. See endorsement and correspondence with freeboard report.

It is FURTHER SUBMITTED the MONTREAL Surveyors be requested to state whether the bottom in way of the boiler room has been cemented as required by the Rules.

They should be informed it is concluded third deck beams amidships, as reported, have not been fitted in this vessel, but they should state if this is so.



© 2021

J.C.D.
18.10.46

Lloyd's Register

Foundation

010466-010477-013