

LLOYD'S REGISTER OF SHIPPING

FOUNDED 1760

RE-CONSTITUTED 1834

Certificate of Class

Twin Screw Motor Ferry "MAKOURIA"
Official Number - *Port of Registry* Georgetown
Owners Government of British Guiana.
Builders, and where and when built Ferguson Brothers (Port Glasgow) Ltd., Port Glasgow, September 1959.

REGISTERED TONNAGES		MOULDED DIMENSIONS	
<i>Gross</i>	560.96	<i>Length</i>	172' 0"
<i>Net</i>	256.09	<i>Breadth</i>	35' 0"
		<i>Depth</i>	11' 3"

This is to Certify *that this Ship has been surveyed by the Surveyors to this Society, and was reported to be, on the 24th September, 1959 at Port Glasgow and on the 1st December, 1959 at Georgetown, Dem. in a fit and efficient condition and in accordance with the Rules; also that she has been CLASSED and entered in the REGISTER BOOK of this Society, with the Character* **⚡A1** *For Service on the Rivers Berbice, Essiquibo & Demerara.*
subject to Periodical Surveys as required by the Rules.

The approved minimum freeboards from the deck line are as follows:—

<i>Tropical</i>	4	<i>feet</i>	1½	<i>inches (T).</i>	<i>Winter</i>		<i>feet</i>		<i>inches (WNA).</i>
<i>Summer</i>	4	<i>feet</i>	¾	<i>inches (S).</i>	<i>North Atlantic</i>		<i>feet</i>		<i>inches (WNA).</i>
<i>Winter</i>	-	<i>feet</i>	-	<i>inches (W).</i>	<i>Allowance for fresh water for all freeboards</i>			1½	<i>inches</i>

Witness my hand,

W. J. Ferguson
Secretary.


Herbert A. Hill
Chairman.

71, Fenchurch Street, London, E.C.3. 5th February 1960.

N.B.—If the ship herein named proceed to sea with a less freeboard than that approved by the Committee, or if the freeboard marks be obliterated or placed higher than the correct position, the class will be liable to be forfeited.

This Certificate is issued upon the terms of the Rules and Regulations of the Society, to which Owners are referred, and which provide that:—

"While the Committees of the Society use their best endeavours to ensure that the functions of the Society are properly executed, it is to be understood that neither the Society nor any Member of any of its Committees is under any circumstances whatever to be held responsible for any inaccuracy in any report or certificate issued by the Society or its Surveyors, or in any entry in the Register Book or other publication of the Society, or for any error of judgment, default or negligence of any of its Committees or any Member thereof, or the Surveyors, or other Officers or Agents of the Society."



© 2021

Lloyd's Register
Foundation