

COPY

LLOYD'S REGISTER OF SHIPPING

2287

COPY FOR LONDON

Port Jacksonville, Florida

29th January 1960



This is to Certify that I have

surveyed the S.S. "APURE" 3164 tons gross of Maracaibo whilst lying on dock and afloat at Merrill-Stevens Dry Dock & Repair Co., Jacksonville, Florida on the 26th December 1959 and subsequently on account of Modified Special Survey and for Damage to indented sheerstrake plating and 1st below deck side in way of pumproom, stated sustained on 10th January 1959 in consequence of vessel being struck by the Barge "TRANSPORT NO. 11" in tow by tug "ULYSSES"

and that I will transmit to the Committee of Lloyd's Register of Shipping, London, a Report, stating that all repairs recommended by me have been completed to my satisfaction, also that I will recommend that she be continued as classed with fresh record of DS 1-60 and notation of Modified Special Survey 1-60 (12 mos.) subject as previously recommended, to 30 fathoms of port chain cable being renewed at the earliest opportunity. (Suffix (DR) to be added to S.S. notation when further repairs effected to shell and deck plating at the Special Survey due January 1961)

Knud Moller

KNUD MOLLER

Surveyor to Lloyd's Register.

KEY TO ABBREVIATIONS

AS	Annual Survey	SS	Hull Special Survey
BiS	Biennial Survey	SS(Dr)	Hull Special Survey (Drilling)
DS	Docking Survey	SS(M)	Hull Special Survey (Modified)
NS	Cargo Battens not fitted (No Sparring)	SS(P)	Hull Special Survey (Progressive)

This Certificate is issued upon the terms of the Rules and Regulations of the Society, which provide that:—

"While the Committees of the Society use their best endeavours to ensure that the functions of the Society are properly executed, it is to be understood that neither the Society nor any Member of any of its Committees is under any circumstances whatever to be responsible for any inaccuracy in any report or certificate issued by the Society or its Surveyors, or in any entry in the Register or other publication of the Society, or for any error of judgment, default or negligence of any of its Committees or any Member thereof, or the Surveyors, or other Officers or Agents of the Society."

Printed in U.S.A.

© 2021

Lloyd's Register Foundation

010484-010494-0382