

EA

28 JUN 1963

51680

Ship's name "ANGELIKI"

Port

P.Sd

No. 7194

3.6.63

ACTION is DEFERRED for examination in dry dock after grounding.

There is an S.R.L.Appendix item.

The PORT SAID Surveyors report (6,63) the ship examined afloat and considerable damages on account of fire were found and extensive repairs recommended.

According to the Owners the ship will proceed to Greece for permanent repairs.

The Surveyors recommend and it is submitted for the consideration of the Committee, that the Notation "Repairs Required - Class Temporarily Suspended" be assigned, but Action continue to be DEFERRED for examination in dry dock after grounding, also pending further information.

IN S.R.L.  
Drydocking (grounding).

IN S.R.L.APPENDIX  
Shell plates G.4 & 5 and  
E.4 & 6 (p.s) indented.

Ship Plans	.....
Ship Research	.....
C.S.S. Records	.....
TO NOTE	

ELB. SURV. TO NOTE  
Noted re electrical cables  
27/7/63

R.F. L  
28/6/63

Reported arrived PIRAEUS 10/6 per Llyds List.  
Not reported under survey in PIRAEUS return of  
21/6



© 2021

Lloyd's Register  
Foundation