

EA

COPY

51680

Ship's name

"ANGELIKI"

Port

P.Sd

No. 7194

3.6.63

ACTION is DEFERRED for examination in dry dock after grounding.

There is an S.R.L. Appendix item.

The PORT SAID Surveyors report (6,63) the ship examined afloat and considerable damages on account of fire were found and extensive repairs recommended.

According to the Owners the ship will proceed to Greece for permanent repairs.

The Surveyors recommend and it is submitted for the consideration of the Committee, that the Notation "Repairs Required - Class Temporarily Suspended" be assigned, but Action continue to be DEFERRED for examination in dry dock after grounding, also pending further information.

IN S.R.L.
Drydocking (grounding).

IN S.R.L. APPENDIX
Shell plates G.4 & 5 and
E.4 & 6 (p.s) indented.

Ship Plans

Ship Research

C.S.S. Records

TO NOTE

*21/10/63. 10.00.00. 10.00.00.
Noted re electrical cables*

Def 7/7/63

*Reported arrived Pireas 10/6 p.m. 10/6 p.m. 10/6 p.m.
Def reported under survey in Pireas return of
21/6*



© 2021

Lloyd's Register
Foundation