

Received from Chief Ship Surveyor

23 JAN 1958

SHIP'S NAME "TOLWORTH" REPORT Nwc. No. 114939.
JD.

Outstanding Conditions of Class:

Subject to set up bottom
plating, etc. (s.s.a.) being examined and dealt with as
necessary next drydocking.

Endorsement of Class (B) (As before or None)

Nature of Present Survey: (Afloat and in dry dock)

Drydocking. Wear and tear repairs to shellplating
and steering gear, etc. Temporary and deferred repairs
to grooved shell plating. Repairs to keelplating aft

Recommendation: on account of damage (cause not stated).

SUBMITTED record of "DS 12,57" be assigned
as recommended, SUBJECT as above, and to grooved
shell plating B.1 (s.s.f.) and D.10 (p.s.a.) being
examined and dealt with as necessary next drydocking,
with Endorsement of Certificate.

DS 12,57. Subject.

ENDORSEMENT/OF CERTIFICATE.

Shell plates C.6, 7 & 8 (p.s.a.)
indented.



© 2021

Lloyd's Register
Foundation

Blk(new)

010589-010604-0343

SUMMARY OF DAMAGE REPAIRS

Renewed

1 Pt

Bracket Floors

Plates

Deck Plates

Decks